(X3) DATE SURVEY

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES

(X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING _ HAL092187 07/17/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **5219 OLD WAKE FOREST RD CARILLON ASSISTED LIVING OF NORTH RALI** RALEIGH, NC 27609 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 000 Initial Comments C 000 This report is of a biennial construction survey done by Bob Getchell on July 17, 2015. This facility was first licensed as a Hoime for the Aged serving 96 residents, 36 of which are in the Special Care Unit, on May 30, 2013. Therefore the facility was surveyed for conformance with the 2005 Rules for the Licensing of Adult Care Homes, and, the 2006 North Carolina State Building Code(s), Section 409.1 Institutional Occupancy, Group I-2. Deficiencies were noted which will require a new plan of correction. C 189 C 189 Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, building components were not maintained in a safe manner. Findings include the following: a) C14 has storage within 18 inches of sprinkler heads, (repaired on-site), b) Corridor Emergency light at D14 is not working. c) Cover removed on PTAC in B4

(X2) MULTIPLE CONSTRUCTION

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE Division of Health Service Regulation

AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED								
		HAL092187	B. WING		07/1	7/2015						
NAME OF I	NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE											
CARILLON ASSISTED LIVING OF NORTH RALI 5219 OLD WAKE FOREST RD RALEIGH, NC 27609												
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	N SHOULD BE COMPLETE							
C 189	Continued From pa	ge 1	C 189									
	maintained in a safe the fire-resistance of This would affect all smoke and fire in the compartment of original Findings include: a. The attic smoke has an unprotected control wire b. The linen closet was unprotected penetral.	barrier wall over room C17 penetration by a HVAC wall and ceiling has an ation by HVAC control wire										
C 199	199 Exhaust Ventilation		C 199									
	provided with exhautwo cubic feet per narequirement does in before April 1, 1984 these specified spa (1) soiled linen stor (2) soil utility room; (3) bathrooms and (4) housekeeping (5) laundry area. (k) This Rule shall facilities with the extended to the cubic feet per nare feet pe	ed in this Paragraph shall be ust ventilation at the rate of ninute per square foot. This tot apply to facilities licensed with natural ventilation in ces: rage; toilet rooms;										

Division of Health Service Regulation STATE FORM

BRP321 If continuation sheet 2 of 3

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01		(X3) DATE SURVEY COMPLETED							
		HAL092187	B. WING		07/17/2015							
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE												
CARILLON ASSISTED LIVING OF NORTH RALI 5219 OLD WAKE FOREST RD RALEIGH, NC 27609												
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	N SHOULD BE COMPLÉTE E APPROPRIATE DATE							
C 199	Continued From pa	age 2	C 199									
		et as evidenced by: vation, the mechanical chen was not maintained										
	Findings include: The exhaust fan in working.	the kitchen mop room is not										
İ												

6899

Division of Health Service Regulation STATE FORM